

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20182343
Address: 1623 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Jason McRoy	Failed	Thursday, December 13, 2018

Corrective Action Required:

2	Misc	<ul style="list-style-type: none">*Nail garage portal sheathing per code 3" oc* Add anchor at east side sill plate splice in garage* Add anchor west side sill plate in garage at splice . Install all exterior doorsAdd anchor at west side garage sill plate at splice within 12 ".* Strap top plate at garage entry hall right side.* Fire block-basement fire place.* Solid block over beams in basement.* Add anchor southwest basement sill plate at splice *Add anchor northeast basement sill plate at splice
---	------	--

Comments: