	Inspection	Summary	
ermit #: PRPWFR2017142 CREEKSIDE AT RA ddress:	•		
	· · · · · · · · · · · · · · · · · · ·	ults noted below. Please ca not cover any work until a	
spection Item: spection:	Inspector:	Outcome:	Date:
spection: EI-Street - Surface Course	•	Outcome: Partial	Date: Monday, December 17, 2018
spection: EI-Street - Surface Course ormational	•		Monday, December
spection: EI-Street - Surface Course formational John DiMauro 12	John DiMauro /17/2018 3:14 PM		Monday, December 17, 2018
spection: EI-Street - Surface Course Formational John DiMauro 12 Phillips Paving wa	John DiMauro /17/2018 3:14 PM as on site to fix and patch	Partial	Monday, December 17, 2018 a ponding problem