CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20170407

Address: 3560 SW HOLLYWOOD DR, Unit:6, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mike Copeland Failed Thursday, April 11,

Commercial 2019

Corrective Action Required:

1 THIRD FLOOR STRAP TOP PLATES AT PLUMBING VENT BORE IN PLATE TWO FAR NORTH

UNTITS. OKAY TO INSULATE 3RD FLOOR ONLY

Corrective Action Required:

2 SECOND FLOOR -BEARING TOP PLATES DRILLED OVER 50% FOR PLUMBING NEED STRAPS.

CHECK ALL

-DRILLING HOLES IN DRAFT STOPS FOR FIBER, STILL WORKING, NOT SEALED

-DOUBLE WALLS NEXT TO TUBS NORTH UNTITS NEED FIRESTOPPED

Comments: