

Inspection Summary

Permit #: PRSUBD20183913, Development - Subdivision
OAKVIEW STORAGE
Address: 1410 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Site Visit	Joe Starlin	Partial	Thursday, April 11, 2019

Informational

1 4-10-19 Talked with Brad the GC he is requesting a wet tap for the water tie it on Douglas due to business operating 24 hours a day.

Informational

2 Joe Starlin 04/11/2019 4:00 PM The beemer crew filled in the core holes on Douglas with flowable fill and fast setting hydraulic cement. They left the street plates on so that the flowable fill can set up completely.

Comments: