## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRLD20190454 Address: 300 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Steve Conrick	Partial	Friday, June 14, 2019
Corrective Action Required:			
1	The area to the north of the big pond needs to be addressed. This can be accomplished with silt fencing, mulch berms, and rock checks. See sheet C411 in the plan set.		
Corrective Action Required:			
2	A construction entrance needs to be added to the area north of the big pond. See sheet C411.		
Corrective Action Required:			
3	the construction entrance at obrien needs to be cleaned up and top dressed with the correct aggregate.		

Comments:

The areas on the south side have been addressed with silt fencing and rock checks.