

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20170409

Address: 3570 SW HOLLYWOOD DR, Unit:7, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Brandon Kalwei	Failed	Thursday, July 11, 2019

Corrective Action Required:

1 Misc

First floor

- Fire block party walls in garage per code
- fire block party wall separating room 107 and 105
- outlets in same wall opening in room 107- fire puddy on outlet boxes
- fire block party walls separating rooms on the south side 1st floor

Second floor

- Fire puddy for outlet boxes in wall separating rooms 210 and 211
- tie down room 211 south side just inside bedroom on left side
- fire block penetration on ride side of bedroom room 211 south side
- fire puddy outlets dividing room 209 and 211
- support strap for duct cut in main room, room 208. Properly support
- fire puddy all outlets in double wall per code, 2nd floor mostly south side

Comments: