PLANS REVIEW CONDITIONS

Permit No:	PRCOM20191371	Date:	August 14, 2019
Project Title:	LIQUOR HOUZZ	Applicant:	
Location:			
205 SE M 291 HV	VY, LEES SUMMIT, MO 64063	ALLIANCE FIRE PROTECTION LLC	
Type of Work:			TH AVE STE 101
Occupancy Group	p: M	KANSAS (CITY, MO 64116
Description: STORE	TENANT FINISH FOR LIQUOR	Primary: (913) 888-0647	

**invite planner to final to verify screeningConstruction Type:Type IIB (Unprotected)Map Page:195H

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review	Reviewed By: Michael Weissenbach	Released for Construction
Sprinkler Plan Review	Reviewed By: Michael Weissenbach	Released for Construction

 2018 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed. (Action Required)
Current annual sprinkler tag to be on the riser.

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.