CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20170409

Address: 3570 SW HOLLYWOOD DR, Unit:7, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Brandon Kalwei Failed Monday, August 26,

2019

Corrective Action Required:

1 THE FOLLOWING

AREAS ARE

First layer of Sheetrock on ceiling on 3rd floor, and stair towers in building 7 approved to continue work.

APPROVED Corrective Action Required:

2 Misc 2nd layer of ceiling on the 3rd floor layers not off set from 1st 24" as per UL

listing,

*****inspection performed on 8/26/19 north and south stair towers need to be re done, leave off piece of sheet rock for next inspection. Sheet rock

seam outside of room 304 is too close from 1st layer to 2nd layer.

Comments: