

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20191320  
Address: 1805 SW MERRYMAN DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                               | Inspector:  | Outcome: | Date:                        |
|---|-------------|----------|------------------------------|
| <b>All Rough Inspection - Residential</b> | Steve Quaid | Failed   | Thursday, September 12, 2019 |

Corrective Action Required:

|   |                          |  |
|---|--------------------------|--|
| 1 | Miscellaneous Correction | ** Draft stop from garage to living area (floor joist area)<br>** Missing double joist hanger at stairs<br>** Foundation lag bolts in basement are loose<br>** Columns in basement need to be anchored<br>** shorter basement I-beam does not have a minimum 1 1/2" bearing on foundation wall |
|---|--------------------------|--|

**Comments:**