## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20191251 Address: 1225 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rough Framing Inspection - Commercial		John Borns	Failed	Wednesday, October 02, 2019
Corrective Action Required:				
1	Misc	TRUSS FABRICATION/ERECTION DRAWINGS REQUIRED FOR FULL FRAMING INSPECTION.		
Corrective Action Required:				
2	Misc	PROVIDE REPORTS OF SPECTIAL INSPECTIONS (A) THROUGH (I) LISTED ON PERMIT DRAWINGS.		
Corrective Action Required:				
3	Misc	COLUMN BASE PLATES ARE BEARING ON FLOOR SLAB. DRAWINGS SHOW BEARING ON FOOTINGS.		
Corrective Action Required:				
4	Misc	W10X45 STEEL BEAM APPEARS TO HAVE NO BOLTED OR WELDED CONNECTION WITH COLUMNS. FABRICATION HOLES ARE UNUSED.		
Corrective Action Required:				
5	Misc	ANCHOR BOLT NUTS NOT - COLUMN BASE PLATES - HOLD-DOWNS AT NE & S	FOUND TO BE TORQUED AT E CORNERS	:
Corrective Action Required:				
6	Misc	NO CITY INSPECTION APPE EAST AND WEST WALLS. S	ROVAL ON RECORD FOR SHE HEATHING IS COVERED.	AR WALL SHEATHING AT

**Comments:**