CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20190654 Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 64081500 NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	n:	Inspector:	Outcome:	Date:
DE - Storn Inspection	n - Sewer Construction n	Ronald Paynter	Partial	Friday, October 25, 2019
Informational:				
1	l T r	Jim's crew has completed storm lines 1 and 16. They are working on storm line 2. Curb inlet box 2-5 was manufactured wrong and has to be replaced. They also set storm lines A and B. Field inlet B-0 is setting high compared to neighboring yard. They need to reshoot elevations and see what is wrong and how to correct the issue. RP 10-18-19		
Informational:				
2		Darren's crew reset the con set 60 ft of storm pipe. RP	rrected curb inlet 2-5 and cu 10-24-19	urb inlet 2-6. They also
Informational:				
3			t 17-1 and laid 150 ft of stor for curb inlets 2-5, 2-6 and 3	•••

Comments: