

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191809
Address: 851 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	Khanh Nguyen	Failed	Wednesday, November 13, 2019

Corrective Action Required:

1	Misc	-COMPLETE INSTALLING HD19 HOLD DOWN. TIGHTEN DOWN HOLD DOWN NUTS. ALL HOLD DOWNS RODS SHALL BE EMBEDDED PER PLAN DETAIL 7/S.4; ANCHOR SILL PLATES WITHIN 12" OF ALL BREAKS -PROTECT PLUMBING WHERE WITHIN 1.25" OF THE WALL PLATES SURFACE -FIRE BLOCK WALL FROM ROOF SPACE
---	------	---

Comments: