CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20191496Address:1800 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
All Rough Inspec Residential	tion - Brandon Kalwei	Failed	Monday, November 18, 2019	
Corrective Actio	Required:			
1 Misc	- fire block penetrat bump out in living ro	 Secure gas line for fire place fire block penetrations at top and bottom plate mechanical and plumbing bump out in living room and hole cut in subfloor install correct dryer box for clothes dryer vent so that vent is not contorted From original shape 		

Ok to insulate

Comments: