CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182604

Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - John Borns Failed Thursday, November

Commercial 21, 2019

Partial Correction:

1 Misc OK TO COVER THREE WALLS AT STAIRWELLS:

AT 1ST FLOOR: STAIRWELLS 1, 2, 3, 4 AT 2ND FLOOR: STAIRWELLS 1, 4, 2, 3 AT 3RD FLOOR: STAIRWELLS 1, 4, 2, 3 AT 4TH FLOOR: STAIRWELLS 3,

BEFORE COVERING INSTALL REINFORCING STRAPS AND BOCA PLATES PER

CODES.

Partial Correction:

2 Misc OK TO COVER WHEN READY WOOD FRAMED WALLS AND SYSTEMS TO BE

ENCLOSED AT:

A.AA FROM A.5 TO A.6 AT SECOND FLOOR ABOVE FIREPLACE AFTER DOUBLE

TOP TOP PLATE IS REINFORCED WHERE NOTCHED FOR PLUMBING;

Partial Correction:

3 Misc OK TO PLACE WHEN READY COMPONENTS OF RATED ASSEMBLY AT CHASE

BEHIND SHOWERS AT: 1ST FLOOR: LEFT WING;

LEFT WING 2ND, 3RD, 4TH FLOORS NOT READY: HOLD-DOWN HARDWARE INSTALLATION NOT COMPLETED. COMPLETE ALL HOLD-DOWNS SO ALL CAN

BE INSPECTED PER WING.

FIRE-BLOCK SHOWER CHASE LIDS WHERE PENETRATED BY PIPE (ANNULA
SPACE).

Comments: