



1100 W Cambridge Circle Drive, Suite 700  
Kansas City, Kansas 66103  
913.627.9040

## DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company  
919 N East Street  
Indianapolis, Indiana 46202

PROJECT: Summit of West Pryor  
Apartments  
Lee's Summit, Missouri

ATTN: Brad Richey

DATE: 11/22/19

WEATHER: Overcast

CFS  
PERSONNEL: M. Simpson / G. Kenyon

TEMPERATURE: 30-45

REPORT #: 19-1125-dr- 16

---

### TYPE OF SERVICE BEING PERFORMED

MASONRY GROUT

DEVIATION FOUND: NO

MASONRY REINFORCING STEEL

DEVIATION CORRECTED:

CONCRETE PLACEMENT

ORIGINAL DEVIATION DATE:

CONCRETE REINFORCING STEEL

---

### WORK ACCOMPLISHED THIS DATE:

#### *M. Simpson*

- Monitored placement of grout and inspected reinforcing steel at A/12 to 11.2 from Elevation 92.4 to 96.4 All wall sections grouted solid.
- Reinforcing steel verified to be in compliance with plans and specifications.
- Inspected reinforcing steel placement for Column footings 7.9/C-D-E-G- & G.9 and 7/C-D-E-F-G- & G.9.
- Reinforcing steel verified to be in compliance with plans and specifications.

#### *G. Kenyon*

- Monitored placement of concrete for Column footings: 7.9/C, D, E and G.9 and 7/C, D, E, F, G and G.9
- One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- Reinforcing steel verified to be in compliance with plans and specifications.