## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20191251 Address: 1225 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	:	Inspector:	Outcome:	Date:
Rough Fra Commerci	ming Inspection - al	John Borns	Failed	Monday, December 16, 2019
Corrective	Action Required:			
1	Misc	2ND FLOOR: MANY WINDOW AND DOOR HEADERS NOT BEARING ON JACK STUDS. SHIM SOLID.		
		PROVIDE ACCESS TO UPPER LEVEL FOR INSPECTION.		
Corrective Action Required:				
2	Misc	2ND FLOOR: NAIL OR STRUCTURAL SCREW TRIPLE CORNER STUDS SECURELY TOGETHER.		
		AT WINDOW FRAMING NAIL OR STRUCTURAL SCREW TRIMMER(KING) STUDS SECURELY TO JACK STUDS.		
		PROVIDE ACCESS TO UPPE	R LEVEL FOR INSPECTION.	

**Comments:**