

Inspection Summary

Permit #: PRSITE20193433, Development - Site
MCKEEVERS MARKET SITE DEVELOPMENT
Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Miscellaneous PWORKS Inspection	Steve Robbins	Passed	Monday, December 23, 2019

Informational

- 1 The contractor installed the irrigation/drain pipe into all the islands that are in the parking lot. They are now clear to backfill.

Comments: