## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20172517

Address: 233 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Inspection Michael Harkins Partial Tuesday, December

31, 2019

Corrective Action Required:

1 LOWER LEVEL PRE-ROCK OK

RC-ok

Fail unit 106 laundry

Fail unit 108 ceiling wall at meter bank

Corrective Action Required:

2 FIRST FLOOR PRE-ROCK OK

RC-ok

Fail unit 202 replace type X on ceiling with type C

Corrective Action Required:

3 SECOND FLOOR PRE-ROCK

RC- ok

1 layer 5/8 type X walls type C ceiling -ok

## **Comments:**