# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20192761

Address: 4704 NE SARATOGA CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Monday, February 10,

Residential 2020

### Corrective Action Required:

1 Misc FRAMING:

- -Install double joist at stair floor opening
- \*\*Code requires double header joist for floor frame opening. You can get the engineer to address this. In case the engineer also requires the double header

joist, then you will have to redo the gas piping and retest.

- -Toe nail all joists to sill plates
- \*\*Not done

### PLUMBING:

-Strap exterior wall and interior bearing wall top plates where bored more than

50%

## **Comments:**