



RFI #122

Brinkmann Constructors
8700 Indian Creek Parkway, Suite 150
Overland Park, Kansas 66210
Phone: (913) 717-9007
Fax: (913) 717-9407

Project: 1260 - Summit at West Pryor
840 West Pryor Road
Lees Summit, Missouri 64081

Missing embed plate at E-1

TO:	Clark Basinger (Bob D Campbell & Sons Structural Engineers)	FROM:	Drew Larkins (Brinkmann Constructors) 8700 Indian Creek Pkwy Overland Park, Kansas 66210
DATE INITIATED:	02/10/2020	STATUS:	Closed
LOCATION:		DUE DATE:	02/11/2020
PROJECT STAGE:	Course of Construction	COST CODE:	
SUB JOB:		SCHEDULE IMPACT:	
COST IMPACT:		SPEC SECTION:	
DRAWING NUMBER:		REFERENCE:	
LINKED DRAWINGS:			
RECEIVED FROM:	JJ Hanses (Bottorff Construction)		
COPIES TO:	Sean Fuller (Brinkmann Constructors), Drew Larkins (Brinkmann Constructors), Dustin Roberts (Brinkmann Constructors)		

Question from Drew Larkins (Brinkmann Constructors) at 05:00 PM on 02/10/2020

Embed plate is missing at column E-1 lvl 99'-3 3/4". Please provide alternative solution for replacement. We propose to drill and epoxy the plate into the wall. Extra depth will be chipped out for the plate so it is flush with the face of the wall.

Official Response: Clark Basinger (Bob D Campbell & Sons Structural Engineers) responded on Tuesday, February 11th, 2020 at 9:34AM CST
see attached

Attachments:
[DOC021120.pdf](#)

BY _____

DATE _____

COPIES TO _____

Brinkmann Constructors

Page 1 of 1

Printed On: 02/11/2020 03:19 PM

BOB D. CAMPBELL & CO.

Structural Engineers

Since 1957

4338 Belleview Ave.

816.531.4144

Kansas City, MO 64111 www.bdc-engrs.com

Project

West River RF1122

Date

Page ___ of ___

