CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20181667

Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

DE - Erosion Sediment Control John DiMauro Failed Monday, March 09,

(ESC) Inspection 2020

Corrective Action Required:

1 Misc EROSION CONTROL INSPECTION FAILD.

There are areas around the basin where the silt fence is down and is allowing

silt to run and collect into the basin.

The area around the creek needs to be graded and protected from site

runoff.

There is an area near the entrance of the site that needs erosion control

devices installed to protect the creek.

Steve Robbins and I met with the developer Doug Park to discuss the erosion control issues on Friday 3/6/2020. Doug said that he will get the areas noted

protected and cleaned up asap.

Comments: