CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182607 Address: 829 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Mark Harding	Partial	Thursday, March 12, 2020
Partial C	Correction:			
1	THE FOLLOWING AREAS ARE APPROVED	OK TO COVER 5/8" MOLD-RESISTENT TYPE "X" GWB AT TUB/SHOWER WALLS: ONE LAYER AT 4TH FLOOR, 3RD FLR, 2ND FLR, 1ST FLR; TWO LAYERS WHERE REQUIRED AT SHEAR WALLS, TUBS/SHOWERS ADJACENT TO STAIRWELLS, ELEVATOR, CORRIDORS - ALL FLOORS		
			LLS 1 LAYER; 2ND LAYER : WALLS 1 LAYER; 2ND LA	
				STANT FIRECODE X GWB AT ACES BETWEEN JOISTS AT
		BASEMENT LEVEL:		
		1ST FLOOR: 1ST LAYE		
		2ND FLOOR: 1ST LAY		
		3RD FLOOR: 1ST LAYE 4TH FLOOR:	:K; ZND LAYEK;	
Correcti	ive Action Required:			

2	STAIR TOWER 1	SOUTH; 4TH FLOOR CEILING-
		WALLS STAIR WELL- 4TH FLOOR 1ST,2ND LAYER UNIT SIDES 3RD FL 1ST LAYER
Correctiv 3	e Action Required: STAIR TOWER 2	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT STAIRWELL WALLS INSIDE FACE AND SPACES BETWEEN JOISTS AT BACKSIDE: SOUTH STAIRWELL #1: BASEMENT: N&E WALLS WELL FACE 1ST & 2ND LAYERS 1ST FLOOR: WELL FACE 1ST LAYER; 2ND LAYER; 2ND FLOOR: WELL FACE 1ST LAYER; 2ND LAYER; 3RD FLOOR: WELL FACE 1ST LAYER; 2ND LAYER; 4TH FLOOR: WELL FACE 1ST LAYER; 2ND LAYER TOWER: WALLS 1ST LAYER; HIGH & LOW CEILINGS 1ST LAYER + 2ND LAYER; NORTH: 4TH FL- 4TH FLOOR 1ST,2ND LAYER UNIT SIDES STAIRWELL : 3RD FL 1ST LAYER;
		OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT STAIRWELL WALLS INSIDE FACE AND SPACES BETWEEN JOISTS AT BACKSIDE: NORTH STAIRWELL #2: BASEMENT LEVEL: WELL FACE 1ST LAYER; 2ND LAYER; 1ST FLOOR: WELL FACE 1ST LAYER; 2ND LAYER 2ND FLOOR: WELL FACE 1ST LAYER; 2ND LAYER 3RD FLOOR: WELL FACE 1ST LAYER; 2ND LAYER 4TH FLOOR: WELL FACE 1ST LAYER; 2ND LAYER TOWER: WALLS 1ST LAYER; HIGH & LOW CEILINGS 1ST LAYER + 2ND LAYER;
Correctiv	e Action Required:	,
4	ELEVATOR 1	1ST,2ND LAYER ELEVATOR SHAFT INSIDE

Comments: