

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSITE20192792  
Address: 2931 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                      | Inspector:   | Outcome: | Date:                           |
|----------------------------------|--------------|----------|---------------------------------|
| <b>DE - Storm - Inlets Clean</b> | John Jackson | Failed   | Wednesday,<br>November 20, 2019 |

Corrective Action Required:

|   |      |   |
|---|------|---|
| 1 | Misc | Contractor poured concrete used for collars and inverts to repair existing storm inlet wall that had to be partly extracted. The contractor (ESS) was informed that this did to meet the requirement for structural soundness. It would require proper reinforcement , concrete and forms.<br>Contractor will continue to update me on repairs. |
|---|------|---|

**Comments:**