CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172535

Address: 269 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Thursday, April 02,

Commercial 2020

Corrective Action Required:

1 THIRD FLOOR BLDG # 17 WEST END -

- 312 FIRE CAULK BORE BOTTOM PLATE BED NEAR PATIO -

- 310 FIRE CAULK BORES BOTTOM PLATE AT TUB & BED CLOSET -

RC CHANNEL COMPLETE IN UNITS NOT DONE ABOVE FRONT ENTRY & STAIRS -

Corrective Action Required:

2 SECOND FLOOR BLDG # 17 WEST END -

- 211 FIRE CAULK TOP PLATE ABOVE SERVICE PANEL, MECH CLOSET DWV LINE

CUT AT HVAC, -

- 212 NAIL GUARD KITCHEN ISLAND, FIRE CAULK 4" LINE IN DEAD SPACE -

- 210 FIRE CAULK 4" LINE IN DEAD SPACE, PATCH HOLE IN SHEAR WALL

BETWEEN JOIST IN BEDROOM, NAIL GAURD KITCHEN ISLAND, FC SPRINKLER IN

LAUNDRY, DWV CUT AT HVAC IN MECH CLOSET -

- 209 FC TOP PLATE COAT CLOSET, FC TOP PLATE & PATCH HOLE COMMON

WALL KITCHEN/LIVING ROOM -

Corrective Action Required:

3 FIRST FLOOR BLDG # 17 WEST END

GARAGE 15 & 16 FURR OUT @ DRAINS

Comments: