

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182609  
Address: 833 NW DONOVAN RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Mark Harding	Partial	Wednesday, April 15, 2020

Partial Correction:

1	ELEVATOR 1	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT ELEVATOR SHAFT: 1ST LAYER 1-4, 2nd layer, ceiling 2nd;3rd,4th
---	------------	---

Corrective Action Required:

2	STAIR TOWER 1	SPACES BETWEEN JOISTS AT BACKSIDE: 3RD FLOOR 1ST BASEMENT- EXTERIOR: 4TH FL- CEILING complete
---	---------------	--

INTERIOR SIDE:  
4TH FL-1ST LAYER;2ND  
BASEMENT-1ST LAYER OK

OUTER SIDE:

Corrective Action Required:

3	STAIR TOWER 2	SPACES BETWEEN JOISTS AT BACKSIDE: 3RD- FLOOR 1ST  CEILING complete-
---	---------------	---

INTERIOR SIDE:  
4TH FL-1ST LAYER;2ND  
BASEMENT-1ST LAYER OK

Corrective Action Required:

4           FOURTH FLOOR

Pre rock tub & showers 4th floor approved 1ST 2ND AT STAIR TOWNERS  
RC CHANNEL UNITS; RC CORRIDOR.

Corrective Action Required:

5           THIRD FLOOR

Pre rock tub & showers 3rd floor approved  
shear walls-ok  
RC CHANNEL

Corrective Action Required:

6           SECOND FLOOR

TUB SHOWERS - 1ST; 2ND Layer  
shear walls-ok

Corrective Action Required:

7           FIRST FLOOR

TUB SHOWERS - 1ST; 2ND Layer  
shear walls-ok

Corrective Action Required:

8           LOWER LEVEL

Elevator Equip, IT, Electrical rooms-2nd layer ok  
shear walls-ok

**Comments:**