

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182611
Address: 901 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Monday, May 18, 2020

Partial Correction:

1	THE FOLLOWING AREAS ARE APPROVED	BEHIND TUBS AND SHOWERS FIRST LAYER FLOORS 1-4 BEHIND TUBS AND SHOWERS SECOND LAYER FLOORS 1-4 ELEVATOR AND STAIRWELL FIRST LAYER FLOORS 1-4 SHEAR WALL FIRST LAYER BEHIND TUBS AND SHOWER FLOORS 1-2 SHEAR WALL 6 FIRST LAYER OSB FLOORS 1-2
---	--	---

Partial Correction:

2	STAIR TOWER 1	4TH FLOOR 1ST LAYER; - 4TH FLOOR 2ND LAYER - -CEILING AND WALL TOP OUT 1ST LAYER-
---	---------------	---

Partial Correction:

3	STAIR TOWER 2	4TH FLOOR 1ST LAYER; - 2ND LAYER FLOORS 1-4 - -CEILING AND TOP OUT 1ST LAYER
---	---------------	--

Partial Correction:

4	ELEVATOR 1	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT ELEVATOR SHAFT: 1ST LAYER FLOORS: 1-4 CEILING:1ST, LAYER - 2ND LAYER FLOORS 1-4 CEILING 2ND LAYER - CEILING 3RD LAYER AND HAT CHANNEL
---	------------	--

Partial Correction:

5 FOURTH FLOOR

Corrective Action Required:

6 THIRD FLOOR

Corrective Action Required:

7 SECOND FLOOR

Corrective Action Required:

8 FIRST FLOOR

1ST FLOOR ELEC ROOM,IT ROOM, ELEV EQIP ROOMS 1ST LAYER -

Corrective Action Required:

9 LOWER LEVEL

Comments: