# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20193476

Address: 4413 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -

Residential

Robb Popp

Failed

Tuesday, May 19, 2020

### Corrective Action Required:

1 Misc

- \*\*DO NOT SHEET ROCK\*\*
- Tighten all bottom plate anchor nuts in basement
- Ledger locks at deck install per manufacturer listing
- Column missing in basement by backdoor pier BEDROOM 5 WALL
- Duct through double header at window by sliding door in basement
- No electrical found below suspended slab in basement
- Fireblock at beam S wall basement by door
- Support joist at cutout below suspended slab stoop
- Protect pex at shower basement N
- Seal pex penetration at top plate bathroom N basement bottom plate bath 2
- Fireblock at 2x6 above fireplace SEAL ALL GAPS
- Complete all fire stopping throughout
- Seal penetrations in top plate great room
- Install truss bracing per plans
- B vent flue within 1" combustible at truss bracing in attic
- -PROVIDE VERTICAL FIRE STOP EVERY 10' ON FURRED OUT EXTERIOR BASE

### **Comments:**