CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172519

Address: 237 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Friday, May 29, 2020

Commercial

Corrective Action Required:

1 LOWER LEVEL SOUTH END -

- 105 FIRE BLOCK DEAD SPACE -

- 107 FIRE BLOCK DEAD SPACE, BOCA PLATES DWV AT FLOOR CLOSET IN

SHOWER BED ROOM - NORTH END NOT READY -

Corrective Action Required:

2 FIRST FLOOR SOUTH END -

- G8 FIRE BLOCK DOUBLE WALL EVERY 10' -

- 205 FIRE BLOCK DEAD SPACE, FIRE BLOCK DOUBLE WALL AT GARAGE EVERY

10' -

- 207 FIRE BLOCK DEAD SPACE -- NORTH END NOT READY -

Corrective Action Required:

3 SECOND FLOOR SOUTH END -

- 305 FIRE BLOCK DEAD SPACE -

- 306 ROOF BOOTS - 307 ROOF BOOTS -

- 308 ROOF BOOTS, FIRE BLOCK DOUBLE WALL EVRY 10', -

- CORRIDOR FIRE BLOCK CHASE -

- NORTH END NOT READY -

Comments: