CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182611 Address: 901 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Rated Assembly Inspection		Inspector: Robb Popp	Outcome: Partial	Date: Wednesday, June 10, 2020		
					Partia	Correction:
1	THE FOLLOWING	BEHIND TUBS AND S	HOWERS FIRST LAYER FLC	ORS 1-4		
	AREAS ARE	BEHIND TUBS AND S	HOWERS SECOND LAYER	FLOORS 1-4		
	APPROVED	ELEVATOR AND STA	IRWELL FIRST LAYER FLOO	RS 1-4		
		SHEAR WALL FIRST L	SHEAR WALL FIRST LAYER BEHIND TUBS AND SHOWER FLOORS 1-2			
		SHEAR WALL 6 FIRST	SHEAR WALL 6 FIRST LAYER OSB FLOORS 1-2			
		SHEAR WALL4 FIRST	LAYER			
		SHEAR WALL 2 FIRST	LAYER			
		SHEAR WALL 6 FIRST	LAYER			
		ELEVATOR EQUIPME	NT ROOM LOWER LEVEL	FIRST LAYER		
		MECHANICAL ROOM	I LOWER LEVEL FIRST LAY	ER		
		CORRIDOR FIRST LA	YER ROOM SIDE LOWER LE	EVEL AND FIRST FLOOR		
		RC CHANNEL WALLS	AND CEILING 4TH FLOOR			
		RC CHANNEL WALLS	AND CEILING 3RD FLOOR			
		RC CHANNEL WALLS	AND CEILING 2ND FLOOF	R		
Partia	Correction:					
2	STAIR TOWER 1	4TH FLOOR 1ST LAYE	ER;			
		- 4TH FLOOR 2ND LA	YER -			
		-CEILING AND WALL	TOP OUT 1ST LAYER-			
		-CEILING AND WALL	S 2ND LAYER			

		MECHANICAL ROOMS 2ND LAYER CEILING 3RD LAYER AND HAT CHANNEL
Partial Co	rrection:	
3	STAIR TOWER 2	4TH FLOOR 1ST LAYER; - 2ND LAYER FLOORS 1-4 - -CEILING AND TOP OUT 1ST LAYER CEILING AND WALLS 2ND LAYER MECHANICAL ROOM 2ND LAYER CEILING 3RD LAYER AND HAT CHANNEL
Partial Co	rrection:	
4	ELEVATOR 1	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT ELEVATOR SHAFT:
		1ST LAYER FLOORS: 1-4
		CEILING:1ST, LAYER
		- 2ND LAYER FLOORS 1-4
		CEILING 2ND LAYER -
		CEILING 3RD LAYER AND HAT CHANNEL
		CEILING 4TH LAYER
Partial Co		
6 Corrective 7	FOURTH FLOOR Action Required: THIRD FLOOR Action Required: SECOND FLOOR Action Required:	SCREW PATTERN ON DRYWALL ENTIRE FLOOR
8 Corrective 9	FIRST FLOOR Action Required: LOWER LEVEL	1ST FLOOR ELEC ROOM, IT ROOM, ELEV EQIP ROOMS 1ST LAYER -

Comments: