

# Inspection Summary

Permit #: PRRES20192660, Building Permit - Residential

Address: 1533 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection:         | Inspector: | Outcome: | Date:                 |
|---------------------|------------|----------|-----------------------|
| Driveway Inspection | Tom Taylor | Partial  | Monday, July 06, 2020 |

Informational

1 On Thursday, 5-14-2020. I performed a driveway inspection. Sub-grade and forming meet city standard and pass inspection.

|                                          |                    |        |                       |
|------------------------------------------|--------------------|--------|-----------------------|
| Occupancy Inspection - Codes Residential | Patrick Schonfeldt | Failed | Monday, July 06, 2020 |
|------------------------------------------|--------------------|--------|-----------------------|

Corrective Action Required

1

- Security screws at back door, provide (2) 3" screws each exterior hinge and strike plate
- Remove all paint covers from smokes
- Final driveway inspection

Comments: