

Inspection Summary

Permit #: PRRES20192660, Building Permit - Residential

Address: 1533 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Tom Taylor	Partial	Monday, July 06, 2020

Informational

1 On Thursday, 5-14-2020. I performed a driveway inspection. Sub-grade and forming meet city standard and pass inspection.

Occupancy Inspection - Codes Residential	Patrick Schonfeldt	Failed	Monday, July 06, 2020
--	--------------------	--------	-----------------------

Corrective Action Required

1 - Security screws at back door, provide (2) 3" screws each exterior hinge and strike plate
- Remove all paint covers from smokes
- Final driveway inspection

Driveway Inspection	Tom Taylor	Passed	Monday, July 06, 2020
---------------------	------------	--------	-----------------------

Informational

1 On Thursday, 5-14-2020. I performed a driveway inspection. Sub-grade and forming meet city standard and pass inspection.

Informational

2 The driveway has been poured and has now passed.

Comments:

