CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182604 Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

r, July 14, 2020		
¢		
CLARIFY LACK OF OVERFLOW PROTECTION FOR HOT WATER HEATERS-ALL UNITS 401-TIGHTEN CENTER POST AT PATIO RAILING, LOOSE OUTLET AT BAR 405- BAD GFCI AT EXTERIOR 407- MISSING SINK FIXTURE IN BATHROOM MECHANICAL CLOSET- MISSING COVER PLATE AND BONDING OF METALLIC BOX AT CEILING ELEVATOR EQUIPMENT ROOM- COMPLETE INSTALLATION OF WIRING		
UNITS 401-TIGHTEN CENTER POST AT PATIO RAILING, LOOSE OUTLET AT BAR 405- BAD GFCI AT EXTERIOR 407- MISSING SINK FIXTURE IN BATHROOM MECHANICAL CLOSET- MISSING COVER PLATE AND BONDING OF METAI BOX AT CEILING		

Comments: