

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Partial	Thursday, July 23, 2020
Corrective Action Required: 1 THE FOLLOWING AREAS ARE APPROVED	pre-inspection walk through.		
Corrective Action Required: 2 STAIR TOWER 1			
Corrective Action Required: 3 STAIR TOWER 2	-STAIRWELL "B"- -1ST FLOOR SHAFT WALL-		
Corrective Action Required: 4 STAIR TOWER 3	STAIRWELL "C" INSIDE FACE: -1ST LAYER 1ST,2ND,3RD,floors - 2ND LAYER 1ST,2ND, 3RD FLOORS -		
Corrective Action Required: 5 FIRST FLOOR	- RC AREA "E" CORRIDOR 119, 122 - - AREA "E" CORRIDOR LIDS 119, -UNITS FURNACE ROOMS,		
Corrective Action Required: 6 SECOND FLOOR	- RC AREA "E" CORRIDOR ceiling & wall 219, - AREA "E" CORRIDOR CEILING 219 COMPLETE, 222 ;		

- ROCK CORRIDOR WALL 3FT DOWN-219,222

Corrective Action Required:

7 THIRD FLOOR

- RC AREA "E" CORRIDOR 319- walls ceiling
- AREA "E" CORRIDOR CEILING
319, 322.
RC CHANNEL- COORIDOR 319,322

CORRIDOR WALL DOWN 3FT

Corrective Action Required:

8 FOURTH FLOOR

- RC AREA "E" CORRIDOR 419, 422 -
- AREA "E" CORRIDOR LIDS 419 COMPLETE, 422 TO STAIRS -

Corrective Action Required:

9 ELEVATOR 1

Corrective Action Required:

10 ELEVATOR 2

Corrective Action Required:

11 ELEVATOR 3

Comments: