CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20201001

Address: 1520 SW GEORGETOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Wednesday, July 29,

Residential 2020

Corrective Action Required:

1 Misc - Garage PFH per plans

- Exterior garage portal strap nails missed interior framing
- Fireblock DWV furred out garage
- Fireblock vertical to horizontal at furred down for DWV and HVAC in garage and seal all gaps
- Fireblock all tub/shower traps
- Seal all top plate penetrations NM penetration at 1st/2nd floor stairway
- Fireblock all chases and dead spaces
- Fireblock all furred downs vertical to horizontal
- Support DWV ever 48" o.c., traps are not considered support
- (3) 2x4 at corner HVAC to dining room framing per plans
- Truss hangers per plans
- EC#2 per plans
- Connect top plates at top stair landing at 2x6 to 2x4 wall
- Anchor all columns to floor in basement
- UFER ground required
- 3" steel column at stairs missing in basement, pier location "A"

Comments: