

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Robb Popp	Partial	Friday, July 31, 2020

Corrective Action Required:

1           FOURTH FLOOR       AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460- 426-  
Corridor 419 to room 439 ok  
Corridor 422 to stairs ok

Corrective Action Required:

2           THIRD FLOOR           Section "E"  
345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing  
ceiling  
  
Corridor 319 to room 364 ok  
Corridor 322 to stairs ok

Corrective Action Required:

3           SECOND FLOOR       Section "E" Ok-241,242,243,244,245,261,262. 226.  
  
Corridor 219 to room 240 ok  
Corridor 222 to stairs ok  
  
-264- shower valve box corridor wall incomplete

Corrective Action Required:

4           FIRST FLOOR           CORRIDOR 119 and 122 CORRECT FIRESTOP THROUGHOUT

-PROVIDE VERTICAL/ HORIZONTAL FIRESTOP AT DEMISING WALL

133

- CORRECT JOIST HANGERS AT PATIO
- PROVIDE PROTECTION PLATE FOR PEX AT DEMISING WALL
- MOVE CLEANOUT AT SHOWER TO ACCESSIBLE LOCATION
- CORRECT SCREW PATTERN AT ROCK BEHIND SHOWER
- PROVIDE NAIL GAURD FOR DWV IN SHOWER

127

- CORRECT FIRE RATING AT SHOWER VALVE IN DEMISING WALL

125

- SEAL PENETRATION IN BOTTOM PLATE AT BATH/ CLARIFY PROPER FIRE ASSEMBLY

**Comments:**