CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20200946

Address: 1631 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Friday, August 14, 2020

Residential

Corrective Action Required:

1 Misc - Garage PFH (portal framing hold down) per plans

- Secure DWV 2" or less at mid point

- Solid block above IvI through living room per plans
- Secure ward flex at fireplace
- Dbl joist hanger at connection above front door
- Ceiling 2x4 laid flat 3' and above needs to be supported to the floor joists

above at basement furred downs to support ceiling load

- Grounding electrode conductor, color code/label at main disconnect

Comments: