

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20190654

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500
NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Hydrant Inspection	Steve Robbins	Partial	Monday, August 31, 2020

Informational:

1 Misc

The existing fire hydrant (21522) has been moved back 10 ft. so when the sidewalk is moved over it the valve and hydrant will not be in the sidewalk path. Greg and Chuck turned off the water, no on was affected. I turned the water back on when the work was complete. The thrust block was poured and had time to set up. The hydrant appears to be low right now, we are going to wait and see when the sidewalk is in it may need to be raised.

Comments: