## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Inspection Michael Harkins Partial Wednesday,

September 02, 2020

Corrective Action Required:

1 Miscellaneous

Correction

RETAIL AREA "B"

-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR

SHEATHING SCREW PATTERN

Corrective Action Required:

2 FIRST FLOOR

-AREAS APPROVED-

AREA "E"

RC CHANNEL WALLS AND CEILINGS CORRIDOR 119

RC CHANNEL ROOMS 121A,124,125,126,127,128,129,133,134,135 WALLS AND

**CEILING** 

- UNITS-126 2ND LAYER -

- 1ST LAYER 124,125,127,128,129, 132, 133,134, 135, 1ST LAYER CORRIDOR AT

THESE UNITS -

Corrective Action Required:

3 SECOND FLOOR \-AREAS APPROVED-

AREA "E"

RC CHANNEL WALLS AND CEILINGS:

**CORRIDORS 219** 

222,226,221A,240-245,261-264

1ST LAYER-222,226

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO ROOM 241, CORRIDOR 222 TO STAIRS

1ST LAYER UNITS: 241,242,243,244,245,262,262,263; 240,264 -

- 2ND LAYER UNITS 241,242,243, 244, 245,262,262,263 -

Corrective Action Required:

4 THIRD FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL - 321A,340,364

RC CHANNEL CORRIDORS- 322,326,327,319

1ST LAYER CEILING- 322, 326 TO ROOM 355.

1STLAYER WALLS CORRIDORS 319 TO ROOM 341,322 TO STAIRS

SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND

**DIMISING WALLS:** 

341,342,343,344,345,361,362,363

- RC CHANNEL

324A,346,348,349,350,351,352,353,354,355,356,357,358,359,360, -

-347 RC @ TRUSS GUSSET REPAIR LIVING ROOM -

- 1ST LAYER UNIT 340, 364, -

Corrective Action Required:

5 FOURTH FLOOR

-AREAS APPROVED-

AREA "E"

RC CHANNEL WALLS AND CEILING 438-453, 459-462 RC CORRIDOR 421A,422,

426, 427

SCREW PATTERN 1ST, 2ND LAYER WALLS CORRIDOR 419 TO ROOM 439 SCREW PATTEN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND

DIMISING WALLS: 439,440,441,442,443,459,460,461

- AREA "E" 4TH FLOOR MECH CHASE OUTSIDE UNITS 448, 450, 451 1ST LAYER --

RC CHANNEL 414A, 444,445,446,447,448,449,450,451

,452,453,454,455,456,457, -

- 1ST LAYER UNITS 438, 462 -

Corrective Action Required:

6 STAIR TOWER 1 STAIR TOWER "A"

AREAS OK:

-1ST LAYER SHEATHING TO 3RD FLOOR;

-2ND LAYER SHEATHING TO 3RD FLOOR

Corrective Action Required:

7 ELEVATOR 2 ELEVATOR "B"

AREAS OK:

-SHEATHING ON NORTH AND SOUTH WALLS (TYPE A)

-FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS -

- 2ND LAYER "B" ELEVATOR WALLS

## **Comments:**