## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial		Inspector:	Outcome:	Date:
		Michael Harkins	Partial	Thursday, September 03, 2020
Corrective 1	Action Required: FOURTH FLOOR	AREA"E"- UNITS-438439,44 426;444,447,448,449,450, Corridor 419 to room 439 -CORRIDOR 419,422,426,4	ok	<del>)</del> -461-462—460-
Corrective	Action Required:	AREA "D" CORRIDOR 412,		
2	THIRD FLOOR	framing ceiling	-	
Corrective 3	Action Required: SECOND FLOOR		241,242,243,244,245, 246, 2	
		-,247,249,250,251,252, 25	3,254,256,257,258,259,260,	

## -248- SEAL DEAD SPACE AT FUTURE SHAFT

		Corridor 219 to room 240 ok Corridor 222 to stairs ok - CORRIDOR 222 FROM STAIRS TO END OF CORRIDOR 226 - SECTION "E" CORRIDOR FRAMING CEILING 229,		
Corrective Acti	e Action Required: FIRST FLOOR	SECTION "D" CORRIDOR CEILING FRAMING 212,		
		BUILDING "B"		
		-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY		
		BUILDING "C" AREAS OK;		
		-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY		
		Section "E" OK-124,125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135		
		Corridor 119 to room 125 ok Corridor 122 to stairs ok CORRIDOR CEILING 112, 129,		
		-Corridor 126 Metal Stud Framing from north exit to line 8.6		
		-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-		
Informational:	onal:	-ROOM 132- -SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT		
5 STAI	R TOWER 3	- STAIR TOWER "C" - - ALL ROUGH APPROVED -		

Comments: