

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Thursday, September 17, 2020

Corrective Action Required:

1	Miscellaneous Correction	RETAIL AREA "B"
---	--------------------------	-----------------

-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR SHEATHING SCREW PATTERN

Corrective Action Required:

2	FIRST FLOOR	-AREAS APPROVED- AREA "E"
---	-------------	------------------------------

RC CHANNEL WALLS AND CEILINGS CORRIDOR 119

RC CHANNEL ROOMS 121A,124,125,126,127,128,129,133,134,135 WALLS AND CEILING

- UNITS-126 2ND LAYER -

- 1ST LAYER 121A, 124,125,127,128,129, 132, 133,134, 135, 1ST LAYER CORRIDOR AT THESE UNITS -

2ND LAYER UNITS 124,125,127,128,129,132,133,134, 135, -

Corrective Action Required:

3	SECOND FLOOR	\-AREAS APPROVED- AREA "E"
---	--------------	-------------------------------

RC CHANNEL WALLS AND CEILINGS:
CORRIDORS 219
222,226, 227, 221A,240-245,261-264 -
- RC CHANNEL CORRIDOR 229 CEILING ONLY -

1ST LAYER-222,226

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO
ROOM 241, CORRIDOR 222 TO STAIRS

1ST LAYER UNITS: 221A,241,242,243,244,245,262,262,263; 240,264 -
- 2ND LAYER UNITS 240,241,242,243, 244, 245,262,262,263, 264, -

- 1ST LAYER MECHANICAL CHASES 2ND FLOOR -

- "E" RC CHANNEL CEILINGS & WALLS
224A,225A,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260, -

Corrective Action Required:

4 THIRD FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL - 321A,340,364
RC CHANNEL CORRIDORS- 322,326,327,319
RC CHANNEL CORRIDOR CEILING ONLY 329,
- RC CHANNEL PARTY WALLS
324A,325A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360, -

1ST LAYER CEILING- 322, 326 TO ROOM 355.

1ST LAYER WALLS CORRIDORS 319 TO ROOM 341,322 TO STAIRS

SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND
DIMISING WALLS:

341,342,343,344,345,361,362,363

- RC CHANNEL

324A,346, 347,348,349,350,351,352,353,354,355,356,357,358,359,360, -

- 1ST LAYER UNIT 321A,324A,325A,340,
346,347,349,350,351,352,353,354,355,356,357,358,359,360,364, -
- 2ND LAYER UNIT 340,364,

- 3RD FLOOR MECHANICAL CHASE 1ST LAYER COMPLETE -
- CORRIDOR 322 1ST LAYER WALL -
- CORRIDOR 326 1ST LAYER WEST WALL -

Corrective Action Required:

5 FOURTH FLOOR

-AREAS APPROVED-
AREA "E"

-RC CHANNEL WALLS AND CEILING 438-453, 459-462 -RC CORRIDOR 421A,422, 426, 427, -
RC CORRIDOR 429 CEILING ONLY -
- RC CHANNEL PARTY WALLS
424,425A,444,445,446,447,448,449,450,451,452,453,454,455,456,457,456,

SCREW PATTERN 1ST, 2ND LAYER WALLS CORRIDOR 419 TO ROOM 439
SCREW PATTEN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND
DIMISING WALLS: 439,440,441,442,443,459,460,461

- AREA "E" 4TH FLOOR MECH CHASE OUTSIDE UNITS 448, 450, 451 1ST
&SECOND LAYER SCREW PATTERN

RC CHANNEL 414A, 444,445,446,447,448,449,450,451
,452,453,454,455,456,457, -

- 1ST LAYER UNITS 438, 462, 421A,424A, 425A -
- 2ND LAYER UNITS 438, 462,421A,425A -
- BLDG "E" PHASE 2 1ST LAYER
444,445,446,447,448,449,450,451,452,453,454,455,
456,457,458 -
2ND LAYER: 444,445,447,448,449,450,451,452,453,454,455,456,
457,458 -
- CORRIDOR 429 1ST LAYER LID -
- CORRIDOR 422 1ST LAYER -
- CORRIDOR 426 1ST LAYER WEST WALL -

Corrective Action Required:
6 STAIR TOWER 1

STAIR TOWER "A"
AREAS OK:
-1ST LAYER SHEATHING TO 3RD FLOOR;
-2ND LAYER SHEATHING TO 3RD FLOOR

Corrective Action Required:
7 ELEVATOR 2

ELEVATOR "B"

AREAS OK:
-SHEATHING ON NORTH AND SOUTH WALLS (TYPE A)
-FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS -
- 2ND LAYER "B" ELEVATOR WALLS
- 1ST LAYER "B" 3RD & 4TH FLOOR SHAFT WALL-
- 2ND LAYER "B" 3RD & 4TH FLOOR SHAFT WALL -

Comments: