

September 15, 2020

New Mark Homes

Re: 1905 SW River Run Drive Lot 9 Whispering Woods Lee's Summit, MO

Apex Engineers Inc. has been retained to address the following items from the rough-in framing inspection:

- 1. The W8x18 above the kitchen has been welded to the Steel beam dividing the kitchen and dining area from the gathering room.
 - A welded web beam to girder connection is an acceptable alternative to detail 3/S3.1 bolted connection.

This report does not constitute approval by the enforcing jurisdiction. Please call if our firm can of further assistance.

LIMITATIONS

The scope of our services includes only those items specifically addressed herein. All other items are outside the scope of this inspection; including any environmental assessment (such as, but not limited to mold, mildew, or presence of any other toxic substance or environmental risks).

In addition, the scope our services does not include any evaluation of the building or site for jobsite safety and/or hazardous conditions. All construction shall be performed in compliance with IRC and OSHA standards at all times. Our firm has not been retained to examine the site or building for any of these conditions. In addition, the contractor shall retain sole responsibility for the quality of work, for adhering to plans, specifications, appropriate codes, and, for repairing defects, deficiencies or omission, regardless of when they are found. By the use of this report it is understood the above conditions are agreed to.

Best Regards, Apex Engineers, Inc.

mule

Daniel W. Meyer, P.E. Project Engineer

