

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Michael Harkins	Partial	Thursday, September 24, 2020

Corrective Action Required:

1	Miscellaneous Correction	RETAIL AREA "B"
		-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR SHEATHING SCREW PATTERN

Corrective Action Required:

2	FIRST FLOOR	-AREAS APPROVED- AREA "E"
---	-------------	------------------------------

RC CHANNEL CEILING 112,129,
RC CHANNEL WALLS AND CEILINGS CORRIDORS 119,122 -
RC CHANNEL ROOMS 121A,124,125,126,127,128,129, 130, 131, 133,134,135
WALLS AND CEILING
- UNITS-126 2ND LAYER -
- 1ST LAYER 121A, 124,125,127,128,129, 130,131, 132, 133,134, 135, 1ST
LAYER CORRIDOR AT THESE UNITS -

2ND LAYER UNITS 121A,124,125,127,128,129,132,133,134, 135, -

Corrective Action Required:

3	SECOND FLOOR	\-AREAS APPROVED-
---	--------------	-------------------

AREA "E"

RC CHANNEL WALLS AND CEILINGS:

CORRIDORS 219

222,226, 227, 221A,240-245,261-264 -

- RC CHANNEL CORRIDOR 212,229 CEILING ONLY -

1ST LAYER-222,226

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO
ROOM 241, CORRIDOR 222 TO STAIRS

1ST LAYER UNITS:

221A,225A,241,242,243,244,245,246,247,249,250,251,252,253,255,256,257,258,259,260,262,262,263; 240,264 -

- 2ND LAYER UNITS 221A,236,240,241,242,243, 244, 245,254,262,262,263, 264, -

- 1ST LAYER MECHANICAL CHASES 2ND FLOOR -

- "E" RC CHANNEL CEILINGS & WALLS

224A,225A,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260, -

- CORRIDOR 226 1ST LAYER WEST WALL -

- CORRIDOR 227,229 CEILING -

Corrective Action Required:

4

THIRD FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL - 321A,340,364

RC CHANNEL CORRIDORS- 322,326,327,319

RC CHANNEL CORRIDOR CEILING ONLY 329,

- RC CHANNEL PARTY WALLS

324A,325A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360, -

1ST LAYER CEILING- 322, 326 TO ROOM 355.

1ST LAYER WALLS CORRIDORS 319 TO ROOM 341,322 TO STAIRS

SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND
DIMISING WALLS:

326,341,342,343,344,345,361,362,363

- RC CHANNEL

324A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360, -

- 1ST LAYER UNIT 321A,324A,325A,340,

346,347,349,350,351,352,353,354,355,356,357,358,359,360,364, -

- 2ND LAYER UNIT

321A,324A,340,347,348,349,350,351,352,353,354,356,357,358,359,360, 364,

- 3RD FLOOR MECHANICAL CHASE 1ST LAYER/2ND LAYER COMPLETE -
- CORRIDOR 319 1ST LAYER -
- CORRIDOR 322 1ST LAYER/2ND LAYER WALLS -
- CORRIDOR 326 1ST LAYER/2ND LAYER WEST WALL
- 1ST LAYER TO MECH SHAFT EAST WALL -
- CORRIDOR 329 LID -
- AREA "D" -
- CORRIDOR 312 RC CHANNEL CEILING -

Corrective Action Required:
5 FOURTH FLOOR

- 4TH FL- -AREAS APPROVED-
- AREA "E" RC CHANNEL AREAS:
- RC CHANNEL UNITS: 438-453, 459-462-424,425A, 414A, 444,445,446,447,448,449,450,451,452,453,454,455,456,457, -
 - RC CORRIDOR 421A,422, 426, 427, -429 CEILING ONLY
 - AREA "E" 4TH FLOOR MECH CHASE OUTSIDE UNITS 448, 450, 451 1ST, 2ND LAYER ;
 - FIRE TAPE COMPLETE -
- BLDG "E" PHASE 2 UNITS:
- 1ST LAYER :444,445,446,447,448,449,450,451,452,453,454,455, 456,457,458 -438, 462, 421A,424A, 425A -
- 2ND LAYER: 444,445,446,447,448,449,450,451,452,453,454,455,456, 457,458, 438, 462,421A,425A -- 419 TO ROOM 439 1ST,2ND LAYER;
- FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS:
- 439,440,441,442,443,459,460,461
- CORRIDOR NUMBERS #:
- 429 1ST LAYER LID -;;439,440,441,442,443,459,460,461;
- WALLS:
- 422 1ST, 2ND LAYER-;
- 426 1ST, 2ND LAYER WEST WALL-;
- " D"
- CORRIDOR 412 RC CHANNEL CEILING -

Corrective Action Required:
6 STAIR TOWER 1

- STAIR TOWER 107 "A" SOUTH
- AREAS OK:
- 1ST LAYER SHEATHING TO 3RD FLOOR;
 - 2ND LAYER SHEATHING TO 3RD FLOOR

Corrective Action Required:
7 ELEVATOR 2

- ELEVATOR 118 "B" WEST CENTER AREAS INSPECTED:
- AREAS OK:
- SHEATHING ON NORTH AND SOUTH WALLS (TYPE A)
 - FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS -
 - 2ND LAYER "B" ELEVATOR WALLS
 - 1ST LAYER "B" 3RD & 4TH FLOOR SHAFT WALL-
 - 2ND LAYER "B" 3RD & 4TH FLOOR SHAFT WALL -

Corrective Action Required:

8	ELEVATOR 3	ELEVATOR 128 "C" NORTH EAST-AREAS INSPECTED: - ELEVATOR 128" C " - - 1ST LAYER WEST WALL 2ND,3RD,4TH FLOORS - - 2ND LAYER WEST WALL 2ND, 3RD & 4TH FLOORS- - 1ST LAYER 4TH FLOOR SOUTH WALL SHAFT & EXTERIOR WALL -
Corrective Action Required:		
9	STAIR TOWER 2	STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED:
Corrective Action Required:		
10	STAIR TOWER 3	STAIR TOWER 123 "C" NORTH AREAS INSPECTED: - 1ST LAYER FLOORS 1 THRU 4 - - RC CHANNEL CEILING -
Corrective Action Required:		
11	ELEVATOR 1	ELEVATOR 102 "A" SOUTH CENTER AREAS INSPECTED:

Comments: