CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20201877 Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Storm Sewer Construction Inspection		John Jackson	Partial	Friday, October 09, 2020	
Informational:					
1 Misc Informational:		Contractor preparing site for installation of storm sewer as-per plan.			
2	Misc	10/1/20 Thursday			
		Wednesday. Curb inlet 2-	Inlet 2-2 and 80' of 24" HDP 3, 2-4, & 2-5 were set in pla ' HDPE, 103' of RCP was inst	ce today approximately	
Informational:					
3	Misc	set Curb Inlet 2-6.	oximately 140' of 15" HDPE o pour inverts for Curb Inlet		
Informational:					
4	Misc	test company Interter PS	base of Curb Inlet 4-1 and 34 I tested street crossing for 1 ry). Contractor poured inver	utilities that were	
Informational:					
5	Misc	10/6/20 Tuesday Contractor installed the S of utilities crossing street	itorm Line #3 & Curb Inlet 3- ts.	1. PSI continued testing	
Informat	ional:				

6	Misc	10/7/20 Wednesday
		Contractor installed Curb Inlet 2-6 & 2-7 and 34' of 15" HDPE pipe from the
		two Curb Inlets.
		Contractor has installed Curb Inlet 5-2 base and ready to install 24" HDPE pipe. 179' of 24" HDPE pipe was installed for Storm Line 5. Inverts and collars were poured for Curb Inlets that were installed yesterday and today.
Inform	mational:	
7	Misc	10/8/20 Thursday
		Contractor installed Curb Inlets 5-3 and 140' of 18" HDPE storm pipe on Line 5.
		Curb Inlets 7-2 and 7-3 were installed and approximately 100' of 18"HDPE
		storm pipe Line 7. The owner of the construction company schedule the
		haphazard construct of Storm Lines due to a back-up in supply by his supplier
		(Possible Covid related).
Inform	mational:	
8	Misc	10/9/20 Friday
		Contractor installed Curb Inlet 7-4 and approximately 42' of 15" RCP pipe on
		Line 7. Inverts and collars were poured on curb inlets.

Comments: