

Inspection Summary

Permit #: PRRES20200990, Building Permit - Residential

Address: 1627 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|---------------------|--------------|----------|-----------------------------------|
| Driveway Inspection | John DiMauro | Partial | Wednesday, October 14, 2020 |

Informational

1 PRE POUR INSPECTION

The forms are set and there appears to be sufficient compacted aggregate.

| | | | |
|---------------------|--------------|--------|-----------------------------------|
| Sidewalk Inspection | John DiMauro | Passed | Wednesday, October 14, 2020 |
|---------------------|--------------|--------|-----------------------------------|

Informational

1 PRE POUR INSPECTION

The forms are set and there appears to be sufficient compacted aggregate.

| | | | |
|----------------------|---------------|--------|-----------------------------------|
| Plot Plan Inspection | Steve Robbins | Failed | Wednesday, October 14, 2020 |
|----------------------|---------------|--------|-----------------------------------|

Corrective Action Required

1 A Public City Sewer manhole 60-264 in the front of this lot has been covered and cannot be found at this time. Please remove the dirt and debris so it can be exposed.

Comments:

