CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20201668

Address: 159 SW M 150 HWY, LEES SUMMIT, MO 64082155 SW M 150 HWY, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Underslab Electrical Inspection Patrick Schonfeldt Failed Friday, October 16,

- Commercial 2020

Corrective Action Required:

2 Misc - JUNCTION BOX WITH SPLICE BELOW SERVICE PANEL ON E SIDE OF BUILDING.

CANNOT HAVE SPLICE BELOW CONCRETE, BOX NOT RATED FOR BURIAL

Corrective Action Required:

3 Misc - JUNCTION BOX WITH SPLICE BELOW SERVICE PANEL ON E SIDE OF BUILDING.

CANNOT HAVE SPLICE BELOW CONCRETE, BOX NOT RATED FOR BURIAL

Comments: