ermit #: PRSUBD20191872, Development - Subdivision MANOR AT STONEY CREEK 4TH PLAT SUBDIVISION IMPROVEMENTS ddress: his work has been inspected and the inspection results noted below. Please call for re-inspection nce all corrective actions have been completed. Do not cover any work until approved.							
				spection Item: nspection:	Inspector:	Outcome:	Date:
				Vater Line - Coliform Tes	st 1 John DiMauro	Partial	Monday, October 19 2020
	10/19/2020 12:05 PM						
John DiMauro 1	10/19/2020 12:05 PM ne samples for the new wat	er main install and delivere	d them to Keystone				
We collected th Lab.		er main install and delivere	d them to Keystone				