## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Michael Harkins	Failed	Thursday, November 12, 2020
Corrective Action Required:			
1 SECOND FLOOR	- SECTION E PHASE 1 JOIST HANGERS CORRIDOR & DECKS -		
Corrective Action Required:			
2 THIRD FLOOR	- SECTION E PHASE 1 JOIST HANGER CORRIDOR & DECKS -		
Corrective Action Required:			
3 FOURTH FLOOR	- SECTION E PHASE 1 JOIST HANGERS CORRIDOR -		
	BELOW HARD LIDS NEED	CORRECTIONS	
	CORRIDOR 419 SEAL PENETRATIONS IN LID, FIRE CAULK PENETRATIONS IN		
	WALLS, SECURE CONDUCT	FORS EVERY 4.5'	
	CORRIDOR 422 SAME AS A	ABOVE	
	CORRIDOR 423 SAME AS A	ABOVE	

## Comments: