CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20203821

Address: 1541 SW MANOR LAKE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Friday, November 13,

Commercial 2020

Corrective Action Required:

1 Misc -Sheetrock inspection required for rated firewall assembly

- Drywall removed on unit from walls and studs, bring to current codes, bring electrical to current codes, AFCI and GFCI protection to current
- Terminate NM to boxes at garage entry under stairs
- Seal data cable top plate penetration, W living room wall
- Seal top plate penetration data, kitchen S wall
- Protection plates at all NM within 1 1/4" of end of framing member
- Charred NM/ceiling box hall ceiling light, master bath
- Charred pex water line above master bedroom and master bath wall
- Burnt/damaged bath exhaust fans and NM at master and hall bath
- Seal penetration at top plate pex master bath wall
- BOCCA protection plates at top and bottom plates for DWV, pex
- Secure all DWV 2" or less at mid point (vertical runs)
- Damaged wiring at HVAC hall bath ceiling
- Damaged NM and shielding, N bedroom, E wall

Comments: