CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Sediment Control (ESC) John DiMauro Failed Monday, November

Inspection 30, 2020

Informational:

1 Misc John DiMauro 11/04/2020 9:22 AM

The erosion control devices need on site need to be corrected and

maintained. Make corrections asap. Photos are uploaded.

Corrective Action Required:

2 Misc John DiMauro 11/30/2020 8:54am

The ESC devices on site need to be corrected and maintained. Additionally,

the inlets need protection installed.

Comments: