

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20202014  
Address: 1523 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Robb Popp	Failed	Friday, December 11, 2020

Corrective Action Required:

1	Misc	-Hole bores through joist less than 2" from end of member for pex, E corner basement and NW corner basement (pex also crimped at bore -Bolt outer ply of rim to ledger at deck and add angel clip to inner ply -Provide (2) bolts per post/rim connection at deck
---	------	---

**Comments:**